

The CFA-08 west side of fence.



Concrete survey marker south end of CFA-08.



The CFA-08 Drainfield signage.

Appendix D Revision to the Comprehensive Facility and Land Use Plan



Deborah W Wagoner

To: Denise R Fitch/FITCDR/CC01/INEEL/US@INEL

Fax to:

Subject: WAG 4 changes to CFLUP

Also, please change restrictions from

"Control access to site (Radiological Work Permit required)." to "Control access at south end of cover to prevent contact with overhead power line."

---- Forwarded by Deborah W Wagoner/WIGG/CC01/INEEL/US on 01/28/03 09:08 AM -----



Deborah W Wagoner

To: Denise R Fitch/FITCDR/CC01/INEEL/US@INEL

12/12/02 01:41 PM

CC:

Fax to:

Subject: WAG 4 changes to CFLUP

Please also change the coordinates for the CFA-08 Drain Field in the CLFUP to:

N 682737.62 E 297120.10 EL 4928.17' N 682640.80 E 297297.38 EL 4928.17'

N 683510.99 E 297772.63 EL 4928.17'

N 683607.81 E 297595.34 EL 4928.17'

---- Forwarded by Deborah W Wagoner/WIGG/CC01/INEEL/US on 12/12/02 01:26 PM -----



Deborah W Wagoner

To: Denise R Fitch/FITCDR/CC01/INEEL/US@INEL

CC: 11/20/02 04:02 PM

Subject: WAG 4 changes to CFLUP

please change to the following:

• The <u>CFA-08</u> Sewage Plant Drain Field has a 5 foot deep native soil cover to limit exposure to cesium-137 contamination. Institutional controls are required.

I think that we should wait for a picture change next spring or fall.

Thanks.


INEEL Waste Area Group Institutional Controls Report

CERCLA Site: CFA-08 Waste Area Group: WAG-4

Location: CFA SEWAGE PLANT DRAINFIELD

Description: CFA-08 is a engineered evapo-transpiration soil cover designed to prevent human exposure to radioactivity. The Sewage Plant Drainfield was determined to pose a threat to humans from cesium-137. Radioactive decay will reduce the cesium-137 concentration to below the 1E-04 future resident risk-based level of 2.3 pCi/g in 189 years. The cover was installed in 2002.

For additional information: Contact the Warning Communication Center (208) 526-1515







Reference Plane: NAD 27 - State Plane System

Institutional Control Scenarios

Time Frame: Remediation Complete/DOE Control

Contaminants of Concern: Cesium-137.

ROD Selected Remedy: Engineered soil barrier and institutional controls.

Use Control Objectives: Maintain integrity of containment barrier

Restrictions: Control access at south end of cover to prevent contact with overhead power

lines. Landfill - no unauthorized intrusion into capped area

Institutional Controls: Visible access restrictions, control of activities (drilling or excavating), publication of surveyed boundaries and descriptions of land-use controls in the

INEEL Land Use Plan

Time Frame: Post Operations/DOE Control

Contaminants of Concern: Cesium-137.

ROD Selected Remedy: Engineered soil barrier and institutional controls.

Use Control Objectives: Maintain integrity of containment barrier

Restrictions: Control access at south end of cover to prevent contact with overhead power lines. Landfill - no unauthorized intrusion into capped area

Institutional Controls: Visible access restrictions (warning signs), control of activities (drilling or excavating), property lease requirements including control of land-use consistent

with the ROD

Time Frame: Post DOE Control

Contaminants of Concern: Cesium-137.

ROD Selected Remedy: Engineered soil barrier and institutional controls.

Use Control Objectives: Maintain integrity of containment barrier

Restrictions: Control access at south end of cover to prevent contact with overhead power

lines. Landfill - no unauthorized intrusion into capped area

Institutional Controls: Property transfer requirements including issurance of a finding of

suitability to transfer and control of land use consistent with the ROD

Close browser window to return to previous screen